

HARVEY DONALDSON & GIBSON

CHARTERED SURVEYORS

Parent to HomeReportScotland.scot







- 1. Single Survey
- 2. Energy Report
- 3. Property Questionnaire



Single Survey

| Property Address | 38 Glenbuchty Place Fraserburgh AB43 9QT | |
|--------------------|--|--|
| | | |
| Customer | Mrs S Mclean (Executor) | |
| | | |
| Date of Inspection | 05/06/2025 | |
| | | |
| Prepared by | Keith Alexander AssocRICS Harvey Donaldson & Gibson Chartered Surveyors | |



TERMS AND CONDITIONS

PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller, It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who will have sufficient current local knowledge of the particular market to competently survey, value and report upon Residential Property. 1

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by checking the adjacent box.

Harvey Donaldson & Gibson is part of the Connells Group. In Scotland, the Connells Group also own

V

Slater Hogg & Howison, Countrywide North and Allen & Harris. Harvey Donaldson & Gibson trades as an entirely separate company and has no financial interest whatsoever in the disposal of the property being inspected. A full list of the Connells group brands is available on https://www.connellsgroup.co.uk/our-group/our-brands/. Harvey Donaldson & Gibson is regulated by RICS for the provision of surveying services. This means we agree to uphold the RICS Rules of Conduct for Firms and all their applicable mandatory professional practice requirements of RICS, which can be found at www.rics.org. As an RICS regulated firm we have committed to cooperating with RICS in ensuring compliance with its standards. The firm's nominated RICS Responsible

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

Principal is Rebecca Freeman FRICS, contact 01332 813096.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential Surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- · the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser: and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report.²

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller:
- "prospective Purchaser" is anyone considering buying the Property.
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

¹Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct

²Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.

PART 2 – DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 2.3.1 Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2.3.2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 2.3.3 Category 1: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is

made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the reinstatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the Surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the Surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the Surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities will not be inspected or reported on.

| Description | The subjects comprise a two storey end terraced dwelling house. |
|---------------------------------|--|
| Accommodation | |
| | Ground floor- Hallway, living room, kitchen. |
| | First floor- Landing, two bedrooms and shower room with w.c. |
| Gross internal floor area (sqm) | 65 |
| | |
| Neighbourhood and location | The property, which was originally erected on behalf of the Local Authority, forms part of an established residential area lying to the west of Fraserburgh town centre. A wide range of facilities and amenities can be found within Fraserburgh. |
| Age | 1955 |
| | |
| Weather | Bright with intermittent light rain showers. |
| | |
| Chimney stacks | Visually inspected with the aid of binoculars where appropriate. |
| | The chimney is of pointed synthetic stone construction. Flashing are formed in lead. |
| | The chimney pot is clay. |

Roofing including roof space Sloping roofs were visually inspected with the aid of binoculars where appropriate.

Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.

The roof is of pitched and hipped design covered with slates with a tiled ridge, cement hips and metal valley.

Access to the roof space is via a hatch on the landing ceiling.

Our inspection of the roof void was restricted due to thickly laid insulation.

The roof is made up of timber rafters and timber sarking boards.

Rainwater fittings

Visually inspected with the aid of binoculars where appropriate.

It will be appreciated that the inspection was carried out during dry weather conditions. Sometimes defects in rainwater goods are only apparent during, or after heavy rainfall.

The gutters and downpipes are of cast-iron construction.

Main walls

Visually inspected with the aid of binoculars where appropriate.

Foundations and concealed parts were not exposed or inspected.

The walls are of solid stone construction pointed externally.

| Windows, external doors and joinery | Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. It should be appreciated that double glazed sealed units do have a limited life expectancy, and defective seals can lead to condensation between the panes, necessitating in the replacement of the unit. This can sometimes only be obvious during adverse weather conditions. The windows are of a double glazed uPVC design. The doors are of timber framed design incorporating double glazed units. |
|-------------------------------------|---|
| External decorations | Visually inspected. |
| | Self coloured uPVC materials. External surfaces are painted, where applicable. |
| Conservatories / porches | None |
| | |
| Communal areas | None |
| Garages and permanent outbuildings | Visually inspected. The outbuilding was only inspected externally, therefore we are unable to comment on internal condition. There is a shed of timber construction under a pitched and felt covered roof. |
| | |
| Outside areas and boundaries | Visually inspected. |
| | The property benefits from private garden grounds to the front, side and rear adequately bounded by blockwork and concrete walls. Garden areas are mainly laid to grass or surfaced with stone chips. Paths are formed in cast concrete and concrete slabs. Vehicular access can be gained to rear. |

| Ceilings | Visually inspected from floor level. Ceilings are plasterboard lined. |
|---------------------------------------|--|
| Internal walls | Visually, in an acted from the autory |
| | Visually inspected from floor level. Using a moisture meter, walls were randomly tested for |
| | dampness where considered appropriate. |
| | The internal walls are of a mixture of solid masonry and plasterboard linings. |
| | |
| Floors including sub floors | Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted. |
| | Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point. |
| | Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch. |
| | The property has fully fitted floor coverings throughout which restricted the scope of our inspection. |
| | No sub-floor inspection was possible due to there being no apparent means of access. |
| | The floors are of solid concrete and suspended timber construction. |
| | |
| Internal joinery and kitchen fittings | Built-in cupboards were looked into but no stored items were moved. |
| | Kitchen units were visually inspected excluding appliances. |
| | Internal joinery comprises timber skirtings, door facings and door surrounds. The doors are timber units with part glazed design. |
| | The staircase is of timber design. |
| | Kitchen fittings comprise a range of wall and base units and work surfaces. |

| | , |
|--------------------------------|--|
| Chimney breasts and fireplaces | Visually inspected. No testing of the flues or fittings was carried out. The chimney breast is plastered masonry. There is a gas fire with back boiler. |
| Internal decorations | Visually inspected. The internal decorations are painted and papered. Some of the ceilings have a textured finish which may contain Artex. |
| Cellars | None |
| Electricity | Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. A mains supply of electricity is connected with power points situated throughout the property. The consumer unit is located in the hall cupboard as is the electrical meter. Wiring, where visible, is sheathed in PVC. |
| Gas | Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. A mains supply of gas is connected. The gas meter is located within an external meter box. |

Water, plumbing and bathroom fittings

Visual inspection of the accessible pipework, water tank or cylinders (if applicable) and fittings without removing any insulation.

Water is supplied from the mains. The visible pipework is copper and plastic.

There is a plastic cold water storage tank located in the roof yold

The shower room contains a three piece suite consisting of a shower enclosure, wash-hand basin and toilet.

Heating and hot water

Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.

No tests whatsoever were carried out to the system or appliances.

The system was not running at the time of our inspection.

The property is centrally heated by means of a gas fired system. Heating to rooms is provided by water filled radiators.

Hot water is supplied from the back boiler behind the gas fire and stored in a foam insulated hot water cylinder located in a bedroom cupboard.

Drainage

Drainage covers etc were not lifted.

Neither drains nor drainage systems were tested.

Mains drainage is understood to be connected.

Fire, smoke and burglar alarms

Visually inspected.

No tests whatsoever were carried out to the system or appliances.

The property has smoke detection devices installed.

Scottish government regulations came into effect on 1st February 2022 which requires each property to have linked smoke and heat detectors and if gas/carbon burning appliances are present then a carbon monoxide alarm fitted. Purchasers should satisfy themselves with regards to compliance.

Any additional limits to inspection

The property was inspected within the limits imposed by closely nailed and fixed fitted carpeting, floor coverings, stored items and furnishings etc.

It will be appreciated that parts of the property, which are covered, unexposed or inaccessible, cannot be guaranteed to be free from defect.


This report does not constitute a full and detailed description of the property and a structural investigation was not carried out. No inspection was undertaken of woodwork or other parts of the structure which are covered, unexposed or otherwise inaccessible and as a result no guarantee can be given that such parts of the structure are free from rot, beetle or other defects.

No removal of internal linings has been carried out in order to ascertain the condition of hidden parts and no warranty can be given regarding the areas not specifically referred to in this report.

The external building fabric has been inspected from ground level only from the subjects grounds and where possible from adjoining public property. Exposure work has not been carried out.

The report does not include an asbestos inspection. However, asbestos was widely used in the building industry until around 2000, when it became a banned substance. If the possibility of asbestos based products has been reported and you have concerns you should engage a qualified asbestos surveyor.


Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of the following 3 categories:



| Structural movement | |
|---------------------|---|
| Repair category: | 1 |
| Notes | No obvious significant structural movement noted, on the basis of a single inspection. All buildings move daily and seasonally as a result of external factors such as gravity, temperature, moisture content and vibrations. Consequently most buildings will have minor non structural cracks related to these factors. Minor cracks can be filled during normal redecoration but often recur seasonally due to normal movement in a building. Non structural cracks of this nature will not be recorded or reported. |

| Dampness, rot and infestation | |
|-------------------------------|--|
| Repair category: | |
| Notes | An electronic moisture meter was used to measure levels of dampness, at random locations, to lower wall surfaces and floors, where accessible and without moving furniture or lifting floor coverings, if present. Woodworm flight holes were noted to the roofing timbers. This appears inactive and our valuation assumes that guarantees are available. |

| Chimney stacks | |
|------------------|--|
| Repair category: | 1 |
| Notes | No obvious significant defects were noted to the chimney head. |

| Roofing including roof space | |
|------------------------------|--|
| Repair category: | 2 |
| Notes | ROOF COVERING: A number of slates were noted to be loose, missing and/or broken. Repairs are required. In the absence of stripping and re-covering, this roof structure will be an increasingly frequent source of maintenance expenditure. ROOF VOID: Woodworm flight holes were noted to the roofing timbers.(see Dampness, rot and infestation). |

| Rainwater fittings | |
|--------------------|---|
| Repair category: | 1 |
| Notes | Cast iron components show signs of corrosion. This will become a progressive defect if left unattended. Allowing leaves, moss, and other debris to accumulate and create blockages is one of the most frequent causes of gutter-related dampness problems. The weight of the accumulated material can cause gutters to leak at joints or even to collapse completely. However, all of this may be prevented by cleaning gutters frequently, preferably twice a year. |

| Main walls | |
|------------------|---|
| Repair category: | 1 |
| Notes | Hairline cracking was noted to mortar pointing. |

| Windows, external doors and joinery | |
|-------------------------------------|--|
| Repair category: | 1 |
| Notes | No obvious significant defects were noted to the windows, doors or external joinery. |

| External decorations | |
|----------------------|--|
| Repair category: | 1 |
| Notes | Metal rainwater fittings are showing signs of corrosion. |

| Conservatories / porches | |
|--------------------------|----------------|
| Repair category: | |
| Notes | Not applicable |

| Communal areas | |
|------------------|----------------|
| Repair category: | |
| Notes | Not applicable |

| Garages and permanent outbuildings | |
|------------------------------------|--|
| Repair category: | 1 |
| Notes | No reportable defect was noted to the outbuilding. |

| Outside areas and boundaries | |
|------------------------------|---|
| Repair category: | 1 |
| Notes | No reportable defects were noted to outside areas and boundaries. |

| Ceilings | |
|------------------|--|
| Repair category: | 1 |
| Notes | There are areas of hairline cracking and minor blemishes to the ceiling surfaces. These can be attended to during the course of normal redecoration. |

| Internal walls | |
|------------------|--|
| Repair category: | 1 |
| Notes | No obvious significant defects were noted to the internal walls. |

| Floors including sub floors | |
|-----------------------------|--|
| Repair category: | 1 |
| Notes | No access to any sub floor was possible at the time of our visit. Within the limitations of our surface inspection there was no indication to suggest significant defects in this area. It will however be appreciated that this area was not inspected and therefore no guarantees can be provided in this regard. Flooring is generally level and firm to the tread. Spillage often occurs to enclosed areas around sanitary fittings and washing appliances with consequent risk of deterioration or decay. The need for repairs can be revealed when coverings and fittings are removed. |

| Internal joinery and kitchen fittings | |
|---------------------------------------|--|
| Repair category: | 1 |
| Notes | Internal joinery is of mixed design and vintage, and although worn in some areas, appears generally serviceable. There are timber panel doors incorporating glazing panels and the presence of safety glass cannot be verified. |

| Chimney breast and fire places | |
|--------------------------------|---|
| Repair category: | 1 |
| Notes | The gas installation appears to be generally commensurate with the age of the installation. It is recommended good practice that all gas installations should be checked periodically. This should be regarded as a routine safety and maintenance check. |

| Internal decorations | |
|----------------------|---|
| Repair category: | 1 |
| Notes | The Artex finishes may contain asbestos fibres. This can only be determined by taking a sample for analysis. Even if the decorative finish does contain asbestos fibres it is not normally considered to be a health hazard provided it is not disturbed, for example it should not be rubbed down during redecoration. |

| Cellars | |
|------------------|----------------|
| Repair category: | |
| Notes | Not applicable |

| Electricity | |
|------------------|---|
| Repair category: | 2 |
| Notes | No obvious significant visual defects noted, however, it is likely that only the most recently rewired properties will have electrical installations that fully comply with current regulations. The installation in this property appears relatively modern but there is no evidence of a recent test. As the property is over 10 years old, it would be prudent to have the electrical system tested. Thereafter it is recommended good practice that all electrical installations should be checked periodically, approximately every five years or when a property changes hands. This should be regarded as a routine safety and maintenance check. |

| Gas | |
|------------------|---|
| Repair category: | 1 |
| Notes | No obvious significant defects noted to the gas installation. All gas appliances should be tested and thereafter maintained by a Gas Safe registered contractor on an annual basis. This should be regarded as a routine maintenance and safety check. |


| Water, plumbing and bathroom fittings | | | |
|---------------------------------------|---|--|--|
| Repair category: | 1 | | |
| Notes | No obvious significant defects noted to accessible plumbing or sanitary fittings. It is essential that all wall linings, tile grout, seals, etc are maintained in good condition. Failure to do so can lead to concealed defects behind wall finishes, and below the bath/shower tray. | | |

| Heating and hot water | | | | |
|-----------------------|---|--|--|--|
| Repair category: | 1 | | | |
| Notes | No obvious significant defect was noted to the heating system, although this has not been tested. The boiler's service history should be checked by referring to the service records. If there is no record of a recent service, the boiler should be checked by an appropriately qualified person. No significant defects were noted to the hot water system, however, it should be appreciated that this has not been tested. | | | |

| Drainage | |
|------------------|---|
| Repair category: | 1 |
| Notes | No obvious significant defects were noted to the drainage system, within the limitations of the inspection. |

Single Survey

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information.



Category 1 No immediate action or repair is needed. Category 2 2

Repairs or replacement requiring future attention, but estimates are still advised.

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. ACCESSIBILITY INFORMATION

Guidance Notes on Accessibility Information

Three steps or fewer to a main entrance door of the property

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

| 1. Which floor(s) is the living accommodation on? | Ground |
|--|--------|
| 2. Are there three steps or fewer to a main entrance door of the property? | Yes |
| 3. Is there a lift to the main entrance door of the property? | No |
| 4. Are all door openings greater than 750mm? | No |
| 5. Is there a toilet on the same level as the living room and kitchen? | No |
| 6. Is there a toilet on the same level as a bedroom? | Yes |
| 7. Are all rooms on the same level with no internal steps or stairs? | No |
| 8. Is there unrestricted parking within 25 metres of an entrance door to the building? | Yes |

4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

The tenure is understood to be Outright Ownership.

The outright ownership details have not been checked by the surveyor, It is assumed that there are no unusually onerous provisions in the title documents.

In line with our normal practice, it is specifically assumed that the property and its value are unaffected by any matters which would or should be revealed to a competent Completing Solicitor by a local search and replies to the usual enquiries, or by any statutory notice and planning proposal.

Where defects or repairs have been identified within this report it is recommended that, prior to entering into any legally binding sale or purchases contracts, further specialists advice and estimates should be obtained, to establish the implications, if any, on a potential offer to purchase or the sale price likely to be achieved for the property.

Previous treatments carried out for wood boring insects in roof timbers. Conveyancer to confirm availability of guarantees.

Checks should be made regarding assumed right of access and maintenance liabilities over the access leading to the driveway at the rear of the property.

The legal adviser should check confirm that the roads and sewers are adopted by the local authority.

It is assumed that there are no statutory, town planning, road or environmental matters which may have an adverse effect on the marketability or value of the property.

Estimated re-instatement cost (£) for insurance purposes

The estimated reinstatement cost for insurance purposes is £290,000 (Two Hundred and Ninety Thousand pounds sterling).

This figure is the estimate of the cost of rebuilding the premises and bears no direct relationship to current market value.

Valuation (£) and market comments

In its present condition our opinion of valuation for the Outright Ownership interest assuming full vacant possession on 05 June 2025 can be fairly stated in the sum of:

£90,000 (Ninety thousand pounds sterling).

Single Survey

| Report author: | Keith Alexander AssocRICS |
|---------------------------|---|
| Company: | Harvey Donaldson & Gibson Chartered Surveyors |
| Address: | Rubislaw Den House 23 Rubislaw Den North Aberdeen AB15 4AL |
| Electronically Signed By: | Keith Alexander AssocRICS |
| Date of report: | 18/06/2025 |

Mortgage Valuation Report

| CASE DETAILS | | <u>, </u> | | | | |
|---|-----------------------------------|--|------------------------------------|------------------------|------------------------------|----------|
| Seller Name(s): | Mrs S Mclean (Executor |) | | | | |
| Property Address: | 38 Glenbuchty Place | | | | | |
| | | | | | | |
| Town: | Fraserburgh | | County | | | |
| Postcode: | AB43 9QT | | | | | |
| Date of Inspection (dd/ | mm/yyyy): | 05/06/2025 | | | | |
| DDODEDTY DETAIL O | | | | | | |
| PROPERTY DETAILS Property Type: | | House | | | | |
| Property Type. Property Style: | | End Terrace | | | | |
| Was the property built | for the public sector? | Yes | | | | |
| For Flats and Maisone | | 103 | Floor the Property is on: | | Number of Floors in the E | Block: |
| Number of Units in the | | | Does the Block have a Lift | } | Transpor or Fredre III and 2 | |
| | | | | | | |
| TENURE | | | | | | |
| Tenure | | Absolute Ownership | | | | |
| If leasehold: | V . | | One of Death (s. s.) | | | |
| Unexpired term (Years |): | | Ground Rent (pa): | | £ | |
| ACCOMMODATION | | | | | | |
| No. of Living Room(s): | | 1 | No. of Bedroom(s): | 2 | No. of Kitchen(s): | 1 |
| No. of Bathroom(s): | | 1 | No. of WC(s): | 0 | No. of Other room(s): | 0 |
| Description of Other ro | om(s): | | | | | |
| Floor Area (m²): | | 78 | Floor Area type: | External | | |
| GARAGES & OUTBUIL | DINGS | | | | | |
| Garages: | | None | | | | |
| Permanent Outbuilding | s: | Shed. | | | | |
| | | | | | | |
| CONCERNATION | | | | | | |
| CONSTRUCTION | | Cally Oters | | | | |
| Wall Construction: | | Solid Stone | | | | |
| Roof Construction: Approximate Year of C | onetruction: | Pitched slate | Any evidence of alterations | or ovtonsions? | | No |
| Alterations / Extensions | | 1955 | Arry evidence of alterations | or extensions? | | INO |
| Alterations / Extensions | s uctalis. | | | | | |
| | | | | | | |
| RISKS | | | | | | |
| | ovement to the property? | No | If Yes, does this appear lor | ngstanding? | | |
| Are there any other risl | | No | | | | |
| If yes to any of the abo | ve, please provide details: | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| SERVICES | | | | | | |
| Electricity: | | Maina | Gas: | Mains | Water: | Mains |
| Central Heating: | | Mains Full | Drainage: | Mains | water. | IVIAITIS |
| | | Heating fuel: Gas | Diamage. | IVIAII13 | | |
| Provide comments: | | Heating type: Radiat | ors | | | |
| | | 0 71 | | | | |
| | | | | | | |
| LEGAL MATTERS | | | | | | |
| | tly legal issues to be verified b | by the conveyancer? | | No | | |
| If yes, please provide of | | , , | | | | |
| , ,, | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| LOCATION | | | | | | |
| LOCATION | | The property is situa | ted within a residential area ir | a town with a sand le- | val of local amonities | |
| Location details: | | The property is situa | ieu wiliiiii a residentiai area if | a town with a good lev | vei oi iocai amenilles. | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| ROADS | | | | | | |
| Road description: | | The road has been a | dopted. | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

Version 1.0 (17/01/2023)

| amenities can be found The subjects were foun Previous treatments ca Checks should be made The legal adviser shoul | within Fraserburgh. d to be in a condition of repair c rried out for wood boring insects e regarding assumed right of ac d check confirm that the roads a | onsistent with the age in roof timbers. Conv cess and maintenance and sewers are adopte | e and type. Areas of routine mai veyancer to confirm availability of e liabilities over the access leaded by the local authority. | ntenance, repair and up of guarantees. ding to the driveway at th | | vide range of facilities and |
|--|---|--|---|---|----------------------------------|------------------------------|
| | | | | | | |
| | | | | | | |
| ESSENTIAL REPAIRS | | | | | | |
| None | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| MORTGAGEABILITY RI | | | | | | |
| The property is suitable | for mortgage purposes subject | to individual lender cr | riteria. | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| VALUATION Market Value in present | condition: | | | | | £ 90000 |
| Market Value after esser | ntial repairs: | | | | | £ 290000 |
| Retention required? | value. | No Retention amo | | | | £ 290000 |
| Are repairs required? | | No Estimated cos | t of repairs: | | | £ |
| | | | | | | |
| DECLARATION | | | | | | |
| Surveyor's Name | Keith Alexander | | Surveyor's Qualifications | ASSOCRICS | Report Date (dd/mm/yyyy): | 18/06/2025 |
| Company Name | Harvey Donaldson & Gibson | Chartered Surveyors | Address | Rubislaw Den House | e 23 Rubislaw Den North Aberdeen | |
| Telephone Number | 01224418749 | | Email Address | Https://homereports | cotiand.scot/ | |
| Surveyor's Signature | | | | | | |

Version 1.0 (17/01/2023)

Energy Performance Certificate (EPC)

Dwellings

Scotland

38 GLENBUCHTY PLACE, FRASERBURGH, AB43 9QT

Dwelling type: End-terrace house
Date of assessment: 05 June 2025
Date of certificate: 13 June 2025

Total floor area: 65 m²

Primary Energy Indicator: 501 kWh/m²/year

Reference number: 0551-1008-7206-6345-8200 **Type of assessment:** RdSAP, existing dwelling

Approved Organisation: Elmhurst

Main heating and fuel: Boiler and radiators, mains


gas

You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

| Estimated energy costs for your home for 3 years* | £5,091 | See your recommendations |
|---|--------|--------------------------------|
| Over 3 years you could save* | £2,916 | report for more information |

* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band E (48)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band E (41)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

| Recommended measures | Indicative cost | Typical savings over 3 years | |
|--------------------------------------|------------------|------------------------------|--|
| 1 Internal wall insulation | £4,000 - £14,000 | £1545.00 | |
| 2 Floor insulation (solid floor) | £4,000 - £6,000 | £273.00 | |
| 3 Heating controls (room thermostat) | £350 - £450 | £195.00 | |

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

| Element | Description | Energy Efficiency | Environmental |
|-----------------------|---|-------------------|---------------|
| Walls | Granite or whinstone, as built, no insulation (assumed) | **** | **** |
| Roof | Pitched, 200 mm loft insulation | **** | ★★★★ ☆ |
| Floor | Solid, no insulation (assumed) | _ | _ |
| Windows | Fully double glazed | ★★★☆☆ | ★★★☆☆ |
| Main heating | Boiler and radiators, mains gas | **** | ★★★★ ☆ |
| Main heating controls | Programmer, TRVs and bypass | ★★★☆☆ | ★★★☆☆ |
| Secondary heating | Room heaters, mains gas | _ | _ |
| Hot water | From main system | ★★★☆☆ | ★★★☆☆ |
| Lighting | Low energy lighting in all fixed outlets | **** | **** |

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 89 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 5.8 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 4.6 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home

| | Current energy costs | Potential energy costs | Potential future savings |
|-----------|----------------------|------------------------|--------------------------|
| Heating | £4,071 over 3 years | £1,671 over 3 years | |
| Hot water | £807 over 3 years | £291 over 3 years | You could |
| Lighting | £213 over 3 years | £213 over 3 years | save £2,916 |
| Totals | £5,091 | £2,175 | over 3 years |

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.


| Recommended measures | | Indicative cost | Typical saving | Rating after improvement | | |
|----------------------|---|------------------|----------------|--------------------------|-------------|--|
| | | indicative cost | per year | Energy | Environment | |
| 1 | Internal wall insulation | £4,000 - £14,000 | £515 | D 63 | D 59 | |
| 2 | Floor insulation (solid floor) | £4,000 - £6,000 | £91 | D 66 | D 62 | |
| 3 | Upgrade heating controls | £350 - £450 | £65 | D 68 | D 65 | |
| 4 | Replace boiler with new condensing boiler | £2,200 - £3,000 | £178 | C 73 | C 72 | |
| 5 | Solar water heating | £4,000 - £6,000 | £57 | C 75 | C 75 | |
| 6 | Replacement glazing units | £1,000 - £1,400 | £66 | C 77 | C 78 | |
| 7 | Solar photovoltaic panels, 2.5 kWp | £3,500 - £5,500 | £409 | B 89 | B 89 | |

Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

- Air or ground source heat pump
- Micro CHP

Choosing the right improvement package





About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Internal wall insulation

Internal wall insulation involves adding a layer of insulation to the inside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. Further information can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk).

2 Floor insulation (solid floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Insulating solid floors can present challenges; insulation laid on top of existing solid floors may impact on existing doors and finishes whilst lifting of a solid floor to insert insulation below will require consideration of the potential effect on both structural stability and damp proofing. It is advised to seek advice from a Chartered Structural Engineer or a registered Architect about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work and may also require a building warrant so it is best to check with your local authority building standards department.

3 Heating controls (room thermostat)

The heating system should have a room thermostat to enable the boiler to switch off when no heat is required. A competent heating engineer should be asked to do this work. Insist that the thermostat switches off the boiler as well as the pump and that the thermostatic radiator valve is removed from any radiator in the same room as the thermostat. Building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority building standards department and seek advice from a qualified heating engineer.

4 Condensing boiler

A condensing boiler is capable of much higher efficiencies than other types of boiler, meaning it will burn less fuel to heat this property. This improvement is most appropriate when the existing central heating boiler needs repair or replacement, however there may be exceptional circumstances making this impractical. Condensing boilers need a drain for the condensate which limits their location; remember this when considering remodelling the room containing the existing boiler even if the latter is to be retained for the time being (for example a kitchen makeover). Building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority building standards department and seek advice from a qualified heating engineer.

5 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

6 Replacement glazing units

Replacing existing double-glazed units with new high-performance units. Building regulations require that replacement glazing is to a standard no worse than previous; a building warrant is not required. Planning permission might be required for such work if a building is listed or within a conservation area so it is best to check with your local authority.

7 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

| Heat demand | Existing dwelling | Impact of loft insulation | Impact of cavity wall insulation | Impact of solid wall insulation |
|------------------------------|-------------------|---------------------------|----------------------------------|---------------------------------|
| Space heating (kWh per year) | 10,645 | N/A | N/A | (4,582) |
| Water heating (kWh per year) | 2,656 | | | |

Addendum

This dwelling has stone walls and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited.

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Keith Alexander

Assessor membership number: EES/021472

Company name/trading name: Harvey Donaldson & Gibson Chartered Surveyors

Address: Rubislaw Den House

23 Rubislaw Den North

Aberdeen AB15 4AL

Phone number: 01224 418749
Email address: help@hdg.co.uk
Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greeners cotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT





| Property address | 38 Glenbuchty place Fraserburgh ab435qt |
|---|---|
| Seller(s) | Mrs S Mclean |
| Completion date of property questionnaire | 23 June 2025 |





Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

| 1. | Length of ownership | | |
|----|--|-------------------------|-----------|
| | How long have you owned the property? 20 years | | |
| 2. | Council tax | | |
| | Which Council Tax band is your property in? (Please tick) | | |
| | A B C D E F G H | | |
| 3. | Parking | | |
| | What are the arrangements for parking at your property? (Please tick all that apply) | | |
| | • Garage | | |
| | Allocated parking space | | |
| | • Driveway 🗵 | | |
| | Shared parking | | |
| | On street | | |
| | Resident permit | | |
| | Metered parking | | |
| | Other (please specify): None | | |
| 4. | Conservation area | | |
| | Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)? | Yes No Don't know | X |
| 5. | Listed buildings | | |
| | Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)? | Yes No | |
| 6. | Alterations/additions/extensions | | |
| a. | (i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)? | Yes No | \square |



| | If you have answered yes, please describe below the changes which you have made: | | |
|----|--|-------------------------------------|---|
| | (ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work? If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking. If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them: | Yes No | |
| b. | Have you had replacement windows, doors, patio doors or double glazing installed in your property? If you have answered yes, please answer the three questions below: | Yes No | |
| | (i) Were the replacements the same shape and type as the ones you replaced? | Yes No | |
| | (ii) Did this work involve any changes to the window or door openings? | Yes No | |
| | (iii) Please describe the changes made to the windows doors, or approximate dates when the work was completed): Please give any guarantees which you received for this work to yestate agent. | | h |
| 7. | Central heating | | |
| a. | Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property — the main living room, the bedroom(s), the hall and the bathroom). If you have answered was or partial – what kind of central | Yes No Partial Gas central heating | X |
| | If you have answered yes or partial – what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air). If you have answered yes, please answer the three questions below: | neacing | |
| | i) When was your central heating system or partial central heating system installed? | 20 years ago | |



| | (ii) Do you have a maintenance contract for the central heating system? | Yes No | × |
|----|--|-----------|---|
| | If you have answered yes, please give details of the company with which you have a maintenance contract: | Sse | |
| | (iii) When was your maintenance agreement last renewed? (Please provide the month and year). | 7/2024 | |
| 8. | Energy Performance Certificate | | |
| | Does your property have an Energy Performance Certificate which is less than 10 years old? | Yes No | × |
| 9. | Issues that may have affected your property | | |
| a. | Has there been any storm, flood, fire or other structural damage to your property while you have owned it? | Yes No | |
| | If you have answered yes, is the damage the subject of any outstanding insurance claim? | Yes No | |
| b. | Are you aware of the existence of asbestos in your property? | | |
| | If you have answered yes, please give details: | Yes No | |
| | | | |



| 10. | Services | | | | |
|-------------------|---|--|------------|-------------------------|--------|
| a. Ple supplie | | connected to your property | and give d | letails of the | |
| Servi | ces | Connected | Supplier | | |
| Gas o | or liquid petroleum gas | Scottish | gas | | |
| | mains or private supply | yes | Mains | ains | |
| Electr | ricity | yes | SSE | | |
| Mains | s drainage | yes | Mains | | |
| Telep | hone | no | Don't hav | e | |
| Cable | TV or satellite | no | Don't hav | e | |
| Broad | lband | no | Don't have | e | |
| | | | | | |
| b. | Is there a septic tank systems, If you have answered yes, below: | em at your property? please answer the two ques | stions | Yes No | X |
| | (i) Do you have appropriat your septic tank? | e consents for the discharg | e from | Yes No Don't know | |
| | | ance contract for your septi please give details of the cointenance contract: | | Yes No | |
| 11. | Responsibilities for share | d or common areas | | | |
| a. | | | | Yes No Don't know | X D |
| b. | Is there a responsibility to on the roof, common stairwell If you have answered yes, p | | enance of | Yes No Don't know | X D |
| C. | Has there been any major roof during the time you ha | epair or replacement of any p ve owned the property? | art of the | Yes No | |



| d. | Do you have the right to walk over any of your neighbours' property — for example to put out your rubbish bin or to maintain your boundaries? | Yes No | X |
|-----|---|-------------------------|--------|
| | If you have answered yes, please give details: | | |
| e. | As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries? If you have answered yes, please give details: | Yes No | X |
| f. | As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.) If you have answered yes, please give details: | Yes No | X |
| 12. | Charges associated with your property | | |
| a. | Is there a factor or property manager for your property? | Yes | |
| | If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges: | No | |
| b. | Is there a common buildings insurance policy? If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges? | Yes No Don't know | |
| C. | Please give details of any other charges you have to pay on a regular upkeep of common areas or repair works, for example to a resident maintenance or stair fund. | | r |
| 13. | Specialist works | | |
| a. | As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property? | Yes No | \Box |
| | If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property. | | |
| | As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property? | Yes No | |
| b. | If you have answered yes, please give details: | | |



| c. | If you have answered yes to 13(a) or (b), do guarantees relating to this work? If you have answered yes, these guarantees purchaser and should be given to your solicitor or estate agent will arrange by your solicitor or estate agent will arrange by You will also need to provide a description out. This may be shown in the original estimates are held by: | and ained. | Yes No | | | |
|-------|---|------------|------------|---------------|------------------|------|
| 14. | Guarantees | | | | | |
| a. | Are there any guarantees or warranties for | any of tl | he followi | ing: | | |
| | | No | Yes | Don't know | With title deeds | Lost |
| (i) | Electrical work | X | | | | |
| (ii) | Roofing | X | | | | |
| (iii) | Central heating | X | | | | |
| (iv) | National House Building Council (NHBC) | X | | | | |
| (v) | Damp course | X | | | | |
| (vi) | Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy) | X | | | | |
| b. | If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s): | | | | | |
| C. | Are there any outstanding claims under ar listed above? | ny of the | guarante | es | Yes No | |
| | If you have answered yes, please give deta | ails: | | | | |
| 15. | Boundaries | | | | | |
| | So far as you are aware, has any boundary of your property been moved in the last 10 years? | | | | Yes No | |
| | If you have answered yes, please give details: | | | | Don't know | |
| 16. | Notices that affect your property | | | | | |
| | In the past three years have you ever red | | | | V | |
| a. | advising that the owner of a neighbouring property has made a planning application? | | | ade a | Yes No | |



| b. | that affects your property in some other way? | Yes No | \Box |
|----|--|-----------|--------|
| c. | that requires you to do any maintenance, repairs or improvements to your property? | Yes No | |
| | If you have answered yes to any of a-c above, please give solicitor or estate agent, including any notices which arrive date of entry of the purchaser of your property. | | |

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s): Mrs S Mclean

Date: 23 June 2025



